

**ELECTRICAL COMPONENT LOCATOR - 1.3L TBI MODELS**

**EFI Main Relay (1.3L TBI)**


**On fuse/relay block, in engine compartment.**

**1994 Suzuki Swift**

**For Xeon**

Copyright © 1998 Mitchell Repair Information Company, LLC

Tuesday, December 02, 2003 06:29PM



**1.3L TBI**

- 1. MAP Sensor
- 2. Throttle Switch Or TP Sensor
- 3. Intake Air Temp. Sensor
- 4. Coolant Temperature Sensor
- 5. Oxygen Sensor (O2S)
- 6. Vehicle Speed Sensor
- 7. A/T Control Module
- 8. DLC (Fuse Block)
- 9. Ignition Coil
- 10. Battery
- 11. Crank Angle Sensor (In Distributor)
- 12. P/S Pressure Switch

- a. Fuel Injector
- b. ISC Solenoid
- c. Fuel Pump Relay
- d. EGR VSV
- e. Malfunction Indicator Light (MIL)
- f. Shift Indicator Light
- g. Ignitor
- h. P/S VSV

- A. ECM
- B. EFI Main Relay
- C. EGR Valve
- D. EGR Modulator
- E. Charcoal Canister
- F. Monitor Coupler Connector (Engine Control)
- G. Injector Resistor
- H. BVSV
- J. Electric Load Diode
- K. Data Link Connector (DLC)
- L. A/C VSV